



GREG BELL Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representatives Present During the Inspection:							
OGM	Pete Hess						
Company	Dave Shaver						

Inspection Report

Permit Number:	C0070033		
Inspection Type:	PARTIAL		
Inspection Date:	Tuesday, February 22, 2011		
Start Date/Time:	2/22/2011 8:12:00 AM		
End Date/Time:	2/22/2011 8:45:00 AM		
Last Inspection:	Tuesday, February 01, 2011		

Inspector: Pete Hess,

Weather: Cold; dark clouds over site.

InspectionID Report Number: 2653

Accepted by: jhelfric 3/3/2011

Permitee: ANDALEX RESOURCES INC Operator: ANDALEX RESOURCES INC

Site: WILDCAT LOADOUT

Address: PO BOX 910, EAST CARBON UT 84520-0910

County: CARBON

Phase III

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages	Mineral Ownership	Types of Operations		
100.00 Total Permitted	✓ Federal	Underground		
78.45 Total Disturbed	☐ State	Surface		
Phase I	County	✓ Loadout		
Phase II	Fee	✓ Processing		

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The site remains in temporary cessation status; there is no activity occurring at the site.

As observed this day, the site is snow covered, although access through and about the site is possible via four wheel drive vehicle.

Other

Inspector's Signature:

Litro Dess

Date

Reprocessing

Tuesday, Februar



Permit Number: C0070033 Inspection Type: PARTIAL

Inspection Date: Tuesday, February 22, 2011

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers	✓			
3.	Topsoil				
<u>—</u>	Hydrologic Balance: Diversions	✓		~	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	Y			
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring	✓			
 4.е	Hydrologic Balance: Effluent Limitations				
 5.	Explosives		✓		
	Disposal of Excess Spoil, Fills, Benches				
	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.					
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control		✓		
15.	Cessation of Operations				
16.	a Roads: Construction, Maintenance, Surfacing				
	o Roads: Drainage Controls	~			
17.					
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.					
22	Other				

Permit Number: C0070033 Inspection Type: PARTIAL

Inspection Date: Tuesday, February 22, 2011

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

An application to transfer the permit from UtahAmerican Energy, Inc. to the InterMountain Power Agency has been submitted to the Division; that transfer process remains pending at this time.

4.a Hydrologic Balance: Diversions

All of the sites culverts and ditches are snow covered. Due to sub-freezing temperatures, there is no runoff occurring. Ponds "A" and "C" do contain frozen meltwater.